## **KPC-1750 Industrial Panel PC**Quick Installation Guide

Thank you for purchasing the Quanmax KPC-1750 industrial panel PC. This document provides information to allow you to quickly install this product.

## **Packing Checklist**

- 1. Take the KPC-1750 out of the packing box and check if the unit is properly secure in the plastic bag.
- 2. Check the contents of the carton box:
  - 1x KPC-1750
  - 1x Power Adapter
  - 1x Power Cord
  - 1x Driver CD

- 1x Quick Installation Guide
- Optional VESA Mounting Kit

## Front & Rear I/Os




Figure 1 Rear I/O

## **Customer Service**

Quanmax Inc.

5F, No. 415, Ti-Ding Blvd. Sec. 2 NeiHu District, Taipei 114, Taiwan

Tel: +886-2-2799-2789 Fax: +886-2-2799-7399 Website: www.quanmax.com

© 2010 Quanmax, an International Corporation. All rights reserved.



Vers 1.00 - P/N: 0D2KPC1750010000